
# PRODUCT MANUAL PRO HEAT BLOW TORCH KIT

4. 360° with anti flare

Part No. 400056

Trade**flame** 



## 360° with Anti flare after 15 seconds Use for Cooking, Heating, Soft Soldering, Hobby, Camping. DIY, Workshop, Heat shrinking and Jewellery/Art

**FEATURES** 

 Piezo Ignition Easy screw on connection Adjustable Flame with on/off control

## **SPECIFICATIONS** Consumption: 80 g/hr

Pro heat blow torch Burning time: 165 min Butane cartridge 220 g ■ Flame length: 180 mm Gas type: Butane

## MAINTENANCE/SERVICING Serviceable components: N/A

Connection type: Screw on fitting

Servicing instructions: N/A

to enable the gas to flow.

**TO EXTINGUISH** 

from the cartridge.

To avoid injury or damage always point the burner away from your

body, other persons or objects and any flammable or combustible

1. Ensure the Flame Control Knob is turned fully clockwise (OFF).

2. Turn the Flame Control Knob a quarter turn counter-clockwise (ON)

3. Press the Trigger to ignite the flowing gas. This torch can be used

in an inverted position after 15 seconds of use.

TRADEPEM INDUSTRIAL PTY LTD.

CONTENTS

Distributed by

screw on fitting

# Tradefiame

TO IGNITE

# on top of the cartridge.

**OPERATION** 

TO ASSEMBLE

or DOT2P.



1. REFER to "HANDLING & STORAGE" details on the gas

2. ALWAYS detach torch from cartridge when not in use.

4. STORE the torch and cartridge in a safe dry place.

3. DO NOT store near source of heat, in a vehicle or in a room used

5. DO NOT breathe gas, fumes, vapour or spray. If inhaled, move the

ENSURE THAT YOU READ AND FULLY UNDERSTAND THE

FAILURE to comply with these instructions and warnings may

result in damage to property, personal injury or death.

ALWAYS detach torch from cartridge when not in use.

ALWAYS inspect the torch before use to ensure it is in good

DO NOT attempt to use the torch if it is leaking, damaged or

CARBON MONOXIDE HAZARD This torch can produce carbon

monoxide which has no odour. Using it in an enclosed space.

DO NOT try to use this tool without first reading and understanding

INSTRUCTIONS AND PRODUCT BEFORE USE.

This Pro heat blow torch should only be used with a Butane gas

nonrefillable cartridge, with the screw type fitting, certified to EN417

It may be hazardous to attempt to fit other types of gas containers.

Note: Before use, check torch seals are fitted correctly and in good

2. Ensure the flame control knob is turned off (OFF) fully clockwise. 3. Keep the cartridge in an upright position and place the torch valve

1. Remove red warning label from torch connection point.









ENSURE flame is completely out after use.

CONTAINS flammable gas under pressure.

DO NOT expose to temperature above 40°C / 104°F.

face, hands, clothing or combustible materials.

• TO AVOID injury or damage only ignite the torch when clear of

ALWAYS inspect your environment before igniting to ensure the

DO NOT disassemble, puncture or incinerate cartridge after use.

CAUTION for maximum protection, always wear safety goggles,

AVOID contact with eyes or skin. In case of contact with eyes,

rinse immediately with plenty of water and seek medical advice.

area is clear of any potential ignition sources or hazards.

Cartridges must be stored and handled in accordance

gloves and other appropriate safety equipment.

PROTECT from direct sunlight.

KEEP out of reach of children.

or soapy water before ignition.

4. Holding the torch, align the cartridge and the appliance thread. and turn the cartridge clockwise. Hand tighten until connection

5. IMPORTANT: Always check for leaks using a leak detection spray

is tight. CAUTION Do not over tighten.

# NEVER leave the torch once lit. Extinguish the torch first ensuring it is completely out and safe before leaving unattended. CAUTION accessible parts may be very hot during and after operation. Care must be taken to avoid accidental burns.

# SMELL GAS OR SEE BUBBLES.

**CHECKING FOR GAS LEAKS** 

Spray Gas Leak Detection Spray (211634) or Gas Leak Detection Foam (400023) around seal and check for bubbles. DO NOT USE IF YOU If you smell gas or see bubbles, the torch is not correctly attached to the gas cartridge. DO NOT IGNITE. Remove the blow torch from the



# ALLOW THE TORCH TO COOL

**CAUTION:** For maximum protection.

always wear safety goggles, gloves or

### TO DISASSEMBLE 1. Follow the EXTINGUISH instructions. 2. Ensure burner has cooled properly.

3. Gently unscrew the torch counter-clockwise. Remove the torch

operation. Care must be taken to avoid accidental burns.

1. Turn the Adjustable Flame Control off (OFF) fully clockwise.

# CAUTION The burner becomes extremely hot during and after

## immediately with plenty of water and seek medical advice. WARNING

**STORAGE** 

# person to a fresh air environment.

cartridge label

for habitation.

## 6. AVOID contact with eyes or skin. In case of contact with eyes, rinse

the instructions.

malfunctioning.

may cause death.

ONLY use in well ventilated areas.